

# DEALER TEKLINE

Adviser D.N  
Date 12-15-86  
Julian 349-15

Call back - a.m.

Year Code	40	7150	CANADA	
Model	718	321	325.5	
Complete VIN				
Mileage				
RENAULT		Jeep	<input checked="" type="checkbox"/>	AMC
Dealer			Sew Dodge	
Caller			Bert D	

## Problem Description

After: 5:00

After: 6:00

Valve Cover - ordered a new valve cover, want bolt up to head.

32 Jeep

TLC 111100

## Attempted Repairs/History

none.

## Suggested Corrective Action

To make cover fit you must drill a top cylinder head.

Diagnostic material available is:

If deficient why:

☒ Adequate  
☐ Deficient

☐ Known problem no field fix  
☐ Service publication deficient\*  
☐ Other\*

See comments below

Comments:

000351

# DEALER TEKLINE

Advisor

Date

Julian

LC

07-01-86

1824-16

Dealer Code

none

COMPLETE VIN

Mileage

1037979 CANADA

912322637723

1300M85A5E1064293

062945

RENAULT

Jeep

✓

Fab

AMC

Dealer

Thomas

Caller

Wayne

After: 5:00

After: 6:00

Problem Description

Valve Cover Melts by  
CART ON ENGINE

TLC 11000

Attempted Repairs/History

Suggested Corrective Action

check for Engine Overheat, or  
loss of lube @ Valve Train.

Diagnostic material available is:



Adequate

Deficient

If deficient why:



Known problem no field fix



Service publication deficient\*



Other\*

Provide comments below

Comments:

000-352

# DEALER TEKLINE

Adviser

Date

Julian

LC

07-11-86

1924-8

Dealer Code	24	45115	CANADA	
Phone	406	327	9200	
COMPLETE VIN	1AC	3C3651	616	205
Mileage	40000			
RENAULT		Jeep		AMC

Dealer

Rice MTRS

Caller Terry

## Problem Description

Valve cover leak oil

After 5:00

After 6:00

TLC 111411

## Attempted Repairs/History

Vehicle has been in 3 times  
for leak

## Suggested Corrective Action

Instructed Tech To perform  
Is note 40E 1A MR 171  
Manual

Diagnostic material available is:

If deficient why:

☒ Adequate

☐ Deficient

Provide comments below

☐

Known problem no field fix

☐

Service publication deficient\*

☐

Other\*

Comments:

000-353

# IntraCompany Correspondence

To: Mr. R. J. Beauchamp Location: Copy To: Messrs.: T. H. Best  
W. Chaldeckas  
R. W. French  
R. I. George  
R. J. Green  
H. A. Johnson  
R. J. Laniewicz  
J. K. Nemeth  
J. A. Seidl  
W. D. Smiley

From: J. A. Hamann Location-Ext: Materials Engineering/  
AMTEK/32620

Subject: RTV Gasket - Date: April 22, 1980  
Nylon Valve Covers.

In the course of development work on the nylon valve cover used for lightweight engines, we evaluated formed-in-place gasket materials. Almost immediately, "gasket in a tube", service part number 8993317, was suspected as being deficient. G.E. was contacted and upon reviewing our data, concurred with our position. Samples from each carton on hand in the tool crib have been checked and some were found to be bad. All were found to be out of shelf life.

## Current Status:

- RTV formed-in-place gasketing, as currently released for plastic valve covers, is a viable sealing system. Adhesion to both nylon and steel is excellent.
- Those valve cover leaks which have shown up in the test program recently are most likely due to deficient material. The record should show that all leakers were engines which had been retrofitted at AMTEK. Materials Engineering knows of no leaks on engines as originally assembled in Kenosha using bulk material.
- The problem of deficient material in the tool crib has been resolved. Materials Engineering has arranged with the local G.E. representative for fresh material to be furnished to the crib (at no cost) on a regular basis. The crib has been advised to discard its current stock. This applies not only to the valve cover but to any sealing job on "D" fleet vehicles where "gasket in the tube" is used.
- G.E. has been requested to review this problem with National Service Parts in Milwaukee.
- Shelf life recommendations as printed on all packages is one year at temperatures not to exceed 80°F. Each tube is date coded on the crimp. The first two letters on year and month. The 1980 year is "K". Months begin with A for January and run through M. The letter I has been deleted from the system.

J. A. Hamann

/js

YEAR	MONTH
H-78	A-Tau
J-79	B-FEB
K-80	C-MAR
A-81	D-APR
	M-MAY

000354



## IntraCompany Correspondence

To:	Location:	Copy To:
J. Y. Vourc'h	Amtek - 33647	F. Bunting
		A. DeBates
From:	Location — Ext:	D. Hittler
R. J. Green	Amtek 32659	J. Lisabeth
		R. Reuter
Subject:	Date:	
<u>Valve Cover Sealing (G.E.)</u>	October 31, 1984	

Russ Tanton of G. E. was in to discuss sealing of the valve cover October 29, 1984. The following information was obtained.

- Olds and Pontiac are continuing with RTV.
- Buick, Chevrolet and Cadillac are going with molded silicon gaskets.
- No one else they know of is using plastic covers although covers and oil pans have been used in production. His opinion is that some people will be reconsidering it in lieu of the die cast costs.
- Both Olds and Pontiac are using some controlled depth at the bolts to maintain .020 or .030 thickness of RTV. *(1673 PASSES P.S.I. IN 10 MINUTES)*
- With this controlled depth they recommend the RTV seal on two parallel planes (no steps, grooves, etc. to shear the RTV).
- Some steel covers have a few dimples in between bolts to keep the cover from contacting the head between two bolts (maintain the RTV thickness).
- We use 1473 RTV in plant currently.

The 1673 which they also recommend and we had tried earlier this year with total failure is being used by Pontiac. It skins over very fast so the cover must be installed quickly (not good for service type installations due to time to install). Also less viscous than 1473.

*L. MORE*

- Temperature cycling test on an engine is the best test method (soak at 20°F and run engine for 200 temperature cycles). Most joints fail in 15 to 20 cycles if they are going to fail.
- Some use pressure test head and cover assembly temperature cycled in place of the whole engine.

000355

Valve Cover Sealing (G.E.)

October 31, 1984

Page 2

- Precured VIP 1443 was also presented. This is heat cured at 350° to 400°F on the cover and looks like an "O" ring permanently bonded to the cover. It is an approach similar to the SWS precured RTV we are testing. They recommend a controlled gap for this material also (.040 on our four cylinder cover). Pontiac is planning on this material on a steel cover for field service.
- The suggested program which we plan to proceed with is as follows:

Six Cylinder

- A. Test 1473 RTV with flat faced covers (ground off) and with inserts installed to control the RTV to .020 thickness.
- B. Test the current cover with flush inserts and a precured bead of 1443.

Four Cylinder

- A. Test 1473 on a modified cover which has a flat face (except for the drip rail and inserts which will control the RTV thickness to .020.
- B. Same cover construction but with precured 1443 VIP and inserts to control the compression to .040 gap.

We will proceed with sample covers for testing.

*R. J. Green*  
R. J. Green

2086R

RJG/kar

000356



## IntraCompany Correspondence

To: List

Location:

Copy To: \*W. Chaldekas

\*R. J. Green

J. A. Homann

\*D. Bittler

\*J. C. Lisabeth

\*E. Schindler

\*W. D. Smiley

O. J. Viengutz

\*J. O. Vourch

From: L. C. Ang

Location: Ext  
AMCEK/33148

Subject: Back-up Material for  
Plastic Valve Covers.

Date: February 14, 1985

\*Present at Meeting

It was suggested by D. Bittler at the February 5th meeting of the plastic valve covers that a back-up material be found for the 940 Rynite (PET) being developed to replace Vydyne (mineral filled nylon).

Ryton R-7, a glass and mineral filled polyphenylene sulfide compound, is being considered. R-7 has a flexural modulus of 2,400,000 psi and heat deflection temperature of 500°F. The following actions will be taken:

1. Test on compatibility with suggested SWS silicone sealant, T400. Bond strength of the sealant to both untreated and "Corona discharge" treated Ryton R-7 plaques was excellent.
2. W. Chaldekas is coordinating the purchase and delivery of a Ryton R-7 shipment to Evert and Jo-Ad for molding trials.
3. 4.2L 6-cylinder valve cover will be molded in production tools at Evert.
4. 3.9L 6-cylinder valve cover will be molded at Jo-Ad with the prototype Kirksite tool.
5. Advanced Material Application personnel will cover the moldings tentatively scheduled for the week of February 25th, pending the arrival of Ryton resin to Evert.
6. Molded parts will be post cured at AMCEK in the Plastic Lab's oven and evaluated.

L. C. Ang

/js

000357



## IntraCompany Correspondence

To:  
R. J. Green

Location:  
Amtek

Copy To:  
D. Hittler  
J. Lisabeth  
R. Reuter  
J.Y. Vourc'h

From:  
C. Miller

Location — Ext:  
Amtek

Subject:  
VALVE COVER  
OIL LEAKAGE STUDY; SUMMARY

Date:  
March 13, 1985

Various changes have been made to the existing I-6 & I-4 valve covers to compensate for oil leaks and associated problems.

One of the first changes in the I-6 cover was an addition of washers to the bolts. This was done in hope of eliminating a torque loss problem. Torque loss is a severe problem since the covers lost an average of half of the specified torque over a short period of time. Two types of washers were evaluated: flat stainless steel washers and spring washers. Although both of these seem to hold the torque for a short period, the long-term effect did show torque loss. This occurred even when initial torque was elevated to 70 in-lbf.

The washers did not solve the torque loss problem, but they helped define the problem. Since the bolts continued to lose torque, but did not rotate, it was determined the cause of loss of torque was due to cold flow of the plastic valve cover. To assist in resolving this problem, another change implemented was a metal insert applied to the bolt holes. This was tested for an extended amount of time with positive results; the average torque stayed very close to the initial torque (70 in-lbf).

Another problem with the I-6 cover was warpage at the flange between bolt holes. A production cover with pre-formed RTV (silicone rubber) was thermal tested. After the first cycle, the bolts lost 49.8% of the initial torque; 56% after this final cycle. Also, after 3 hot-cold cycles, the cover warped considerably between the bolt holes on the right (spark plug) side of the cover.

In order to counteract this warpage, a more rigid material, Rynite 940 cover was molded for the I-6 and I-4 engine. Valve cover oil leakage Study. The Rynite I-4 cover was tested with a pre-formed bead of RTV and also with metal inserts in the bolt holes, creating a .020 inch gap. A similar arrangement for the production cover was made and these two covers were thermal cycled (5 cycles: -40°F 300°F). Results showed torque remained

000358



the same throughout all cycles for the Rynite cover and during the 4th cycle, a loss of 1.5% occurred for the production I-6 cover. Also, the final cover to head distance was greater for the production cover by 80%.

Besides thermal testing of the Rynite cover, a few I-4 and I-6 covers were molded and tested on fleet and lease vehicles. Tested covers included metal inserts in the bolt holes providing .020 inch gap and on the I-6, shims were placed on the left side to create the same depth. A preformed bead of RTV was used as a sealant.

In general, results show practically no torque loss, although most of the covers did develop oil leaks. This was due to the slightly out of print covers which resulted from problems in manufacturing the new material covers.

Production tools have been used to mold a limited number of valve covers in Rynite. After being inspected for dimensional stability, these covers will be tested on selected fleet and lease vehicles. These covers will also have spacers, pre-cured RTV and shims (I-6 only).

A thorough examination of these vehicles will determine whether the above stated methods will eliminate the oil leakage problem of AMC I-6 and I-4 valve covers.

*C. Miller*

C. Miller

Z321R/008ZR/85  
CM/fw

000359



## IntraCompany Correspondence

To:

J. Waterworth

Location:

Amtek

Copy To:

R. J. Green  
R. G. Kurowski  
R. H. Reuter  
C. P. Theodore

From:

W. J. Robertz

Location — Ext:

Amtek

Subject:

4.2L Production Engine  
Rocker Arm Cover

Date:

July 11, 1986

The rocker arm covers on eight production engines EBU, received from Kenosha were evaluated for leaks and fastener torques. Each engine was pressurized to 5PSI and checked for leaks with "snoop"; none were found. Fastener torque to tighten torques were taken and recorded. The 7/16-14 retainers nuts were torqued to 35 ft/lbs in production, the torque to tighten of these retainers ranged from 30-35 ft/lbs. The 1/4-20 shoulder bolts were torqued to 55 in/lbs in production and their torque to tighten ranged from 70-110 in/lbs.

W. J. Robertz



3889C/dma

000360

# TORQUE TO TIGHTEN

● 7/16-14 RETAINER NUT FT/LBS

○ 1/4-20 SHOULDER BOLT IN/LBS



FRONT



1000361

*File*

## IntraCompany Correspondence

To:

E. H. Reuter

Location:

AMTEK

Copy To:

C. P. Theodore

R. J. Green

R. G. Kurrowski

J. Waterworth

From:

W. J. Robertz

Location — Ext:

AMTEK

Subject:

Rynite Valve Cover Status

Date:

July 21 1986

This report summarizes the status of the Rynite valve cover fleet through July 21, 1986.

*W. J. Robertz*  
W. J. Robertz

WJR/va  
Attachments  
3797C/0033C

000362

Use	Usage	Displ.	NY	Date Checked	Mileage at Check/HP.	Remarks
L. Lisabeth	General Service	4.2L	81-Concord	7/14/86	3997	No visual leaks * (o)
I. Gordon	General Service	4.2L	81-Spirit	6/11/86	4320	No visual leaks * (o)
L. Bramblett	General Service	4.2L	81-Concord	6/11/86	3131	No visual leaks * (o)
Mallett	General Service	4.2L	81-Concord	7/15/86	4076	No visual leaks * (o)
Tozer	General Service	4.2L	81-Concord	7/11/86	9000	No visual leaks * (o)
Sheppard	General Service	4.2L	81-Concord	7/14/86	1750	No visual leaks *
E. J. Stoecker	General Service	4.2L	82-Eagle	6/3/86	7000	No visual leaks
L. Knoespel	General Service	4.2L	82-SX4	7/15/86		Installed new cover * (o)
H. T. Flood	General Service	4.2L	82-Concord	6/10/86	3759	No visual leaks
Wojtan	General Service	4.2L	82-Concord	7/15/86	3763	No visual leaks * (o)
Cowser	General Service	4.2L	82-Spirit	6/10/86	3759	No visual leaks * (o)
Federoff	General Service	4.2L	82-Concord	6/3/86	2732	No visual leaks
Madoud	General Service	4.2L	82-Concord	6/6/86		New cover installation
Gentner	General Service	4.2L	82-Concord	7/8/86		New cover installation
Trate	General Service	4.2L	82-Concord	7/8/86		New cover installation
ter	General Service	4.2L	82-Concord	7/3/86		New cover installation
mons	General Service	4.2L	83-Eagle	6/12/86	1238	No visual leaks (No longer in service)
F. Bargende	General Service	4.2L	86-Eagle	7/10/86	8700	No visual leaks (No longer in service)
D. Underhill	General Service	4.2L	85-GW	7/14/86	13100	No visual leaks
Morgan	General Service	4.2L	85-GW	7/16/86	4000	No visual leaks
J. Sareker	General Service	4.2L	85-GW	5/22/86	2371	No visual leaks
no DSG 014	General Service	4.2L	85-GW	6/3/86	2857	No visual leaks (No longer in service)
Dyno DSG 016	General Service	4.2L	85-GW	6/3/86	3391	No visual leaks (No longer in service)
Zonca	General Service	4.2L	85-Eagle	6/3/86	—	Vehicle no longer in service
G. Dell Garage	General Service	4.2L	86-GW	6/4/86	2400	No visual leaks
H. E. Wolfe	General Service	4.2L	86-GW	4/23/86	3550	No visual leaks (No longer in service)
Hesse	General Service	4.2L	86-GW	4/26/86	7800	No visual leaks (No longer in service)
Kent	General Service	4.2L	86-GW	7/7/86	6000	No visual leaks (No longer in service)
ay	General Service	4.2L	86-GW	4/24/86	10,300	No visual leaks (No longer in service)
J. Sullivan	General Service	4.2L	86-GW	5/20/86	6000	No visual leaks (No longer in service)
Wimmercuth	General Service	4.2L	86-GW	7/16/86	5000	No visual leaks
G. Wilberger	General Service	4.2L	86-GW	7/15/86	7000	No visual leaks

0101353

Name	Usage	Displ.	RY	Date Checked	Mileage at Check/Hr.	Remarks
Dyno D4C-026	Durability	2.46L	86-XJ	7/14/86	39,935	No visual leaks (No longer in service)
'SC-009	Durability	2.46L	86-XJ	7/14/86	91,000	No visual leaks (No longer in service)
Dyno D4C-064	Durability	2.46L	86-XJ	7/14/86	30,000	No visual leaks (No longer in service)
Dyno D6C-015	Durability	2.46L	86-XJ	7/14/86	28,430	No visual leaks (No longer in service)
Dyno-GP-1	Durability	2.46L	86	7/11/86	2285.4 Hrs.	No visual leaks (No longer on test)
Dyno-GP-2	Durability	2.46L	86	7/11/86	1763 Hrs.	No visual leaks (No longer on test)
Dyno-GP-3	Durability	2.46L	86	7/11/86	1260 Hrs.	No visual leaks (No longer on test)

- \* No bolt hold down holes on the ends
- PCV grommet hole dimension over size on proto covers causing seepage
- (o) Modified cover
- (A) Original cover was cracked at installation

5796-0033C  
MJR/ra

000364



## Memorandum

To:	Location:	Copy To:
P. H. Reuter	Amtek	R. J. Green
From:	Location - Ext:	R. G. Kurowski
W. J. Robertz	Amtek/3-3395	J. Watworth
Subject:	Date:	C. P. Theodore
<u>RYNITE VALVE COVER STATUS</u>	December 19, 1986	

This report summarizes the status of the Rynite valve cover fleet through December 12, 1986. The sixteen 1985/1986 PEP lease vehicles are now all turned in and are no longer available for evaluation. These sixteen vehicles, with a combined accumulation of 90,463 miles, did not show any visual signs of oil leaks. The seventeen 1981/1984 vehicles had a combine accumulation of 143,513 miles, with the exception of one vehicle there have been no leaks. A very small percent of the 1981 vehicles will and do have a slight weepage at the ends of the rocker cover. This occurs due to the fact that on this model year there are no holes drilled and tapped in the ends of the cylinder head for fasteners. This weepage, that causes dampness, has not created a problem.

*W. J. Robertz*  
W. J. Robertz

WJB/ncw  
0278C

IV

000:365  
000:366






# I.S.

INFORMATION SERVICE  
SERVICE INFORMATION  
SERVICE INFORMATION  
INFORMACIONES SERVICIO  
INFORMAZIONI SERVIZIO  
SERVICEINFORMATIE  
SERVICEINFORMATION  
INFORMACAO SERVICO

3E

MAY 1986  
ENGLISH EDITION

1986 AMC EAGLE  
1986 JEEP GRAND  
WAGONEER/TRUCK  
1987 WRANGLER



## ENGINES

Attention: Workshop, Parts Department

### 4.2LITER REVISED CYLINDER HEAD COVER

Starting in April, 1986 all 4.2L (258 cu. in.) engines will be equipped with a new cylinder head cover, PN 8933 003 691.

The new cylinder head cover comes equipped with a pre-cured RTV seal. The new cover is reusable as long as the sealer and/or cover are not damaged during cylinder head cover removal/installation.

Follow the procedure below for proper cylinder head cover removal/installation.

#### PROCEDURE

##### Removal

1. Disconnect the battery negative cable.
2. Remove the air cleaner assembly and the PCV molded hose.
3. Disconnect the distributor vacuum advance hose at the distributor.
4. Disconnect the fuel line at the fuel pump. Rotate the line as necessary to provide clearance for removal of the cylinder head cover.

5. Remove the PCV valve from the grommet in the cover. Disconnect the PCV shut-off valve vacuum hose.

6. Remove the vacuum switch and bracket assembly from the cover.

7. Remove all necessary vacuum and air hoses to provide clearance for removal of the cover.

**NOTE:** Identify and tag the hoses for installation reference.

8. Remove the cylinder head cover retaining nuts and bolts.

9. Lift and tilt the cylinder head cover toward the passenger side and remove the cover.

Inspect the cover for cracks and the sealer for cracks and/or damage that may have occurred during removal. Replace the cover if it is cracked or damaged in any way.

**NOTE:** Small cracks in the sealer are allowed and can be repaired by applying RTV sealer to the cracked area before cylinder head cover installation.

#### Installation

1. If a replacement cover is being installed, transfer the PCV valve grommets and oil filler cap from the original cover.

2. Clean the cover and cylinder head sealing surface using a clean, dry cloth.

3. Install the cover, shoulder bolts and retaining nuts.

4. Tighten the shoulder bolts and retaining nuts to 5.5 to 8.0 N-m (50 to 70 in. lbs.) torque.

5. Connect the fuel line and distributor vacuum advance hose.

6. Install the vacuum switch and bracket assembly on the cover.

7. Reposition and/or connect all the air and vacuum hoses that were moved for cover removal clearance.

8. Connect the PCV valve and the PCV shut-off valve hoses.

9. Install the air cleaner assembly and hoses.

10. Connect the battery negative cable.

11. Check the engine oil level and add if necessary.

#### FILING INSTRUCTIONS

Record this I.S. Note in M.R. 251 page B-133, M.R. 253 page B-59, M.R. 279 page B-118 and file it in MOT. 4.2.



# I.S.

INFORMATIONS SERVICE  
SERVICE INFORMATION  
SERVICE INFORMATION  
INFORMACIONES SERVICE  
INFORMACIONES SERVICE  
SERVICEINFORMATION  
SERVICEINFORMATION  
INFORMACAO SERVICE

46E

MAY 1986  
ENGLISH EDITION

1981½-1986 AMC/JEEP  
WITH 4.2L (258 cu. in.)  
ENGINE



## ENGINES

Attention: Workshop, Parts Department

### 4.2 LITER REVISED CYLINDER HEAD COVER

A new cylinder head cover kit PN 8983 503 343 has been released for service use on 1981½ to 1986 AMC/JEEP vehicles equipped with a 4.2L (258 cu. in.) engine.

1981½-1983 vehicles will require that the cylinder head be drilled and tapped for a 1/4" x 20 threaded insert. Obtain locally a Helicoll, Time-Sert or equivalent threaded insert kit.

**NOTE:** 1981½ models can be identified by having cylinder head cover retaining screws located at the front and rear of the cylinder head.

The new cylinder head cover comes equipped with a pre-cured RTV seal and is secured to the cylinder head with special shoulder bolts, and unique retaining nuts.

Follow the procedure included in the cylinder head cover kit.

### PARTS INFORMATION

DESCRIPTION	QUANTITY	PART NUMBER
Kit, Cylinder Head Cover	1	8983 503 343
Contents:		
Cover, Cylinder Head	1	
Bolt, Shoulder	4	
Bolt, Shoulder, Short	1	
Bolt, 7/16	2	
Bolt, Stud-1/2	1	
Bridge	2	
Nut, Retainer	4	
Helicoll 1/4 x 20	3	
Installation Sheet	1	

000-369

## SRT/TIC INFORMATION

OPERATION DESCRIPTION	NUMBER	TIME	TIC
Co. Kit, Cylinder Head Cover-Install 1991½-1983 models 1983-1986 models	0117 0113	1.7 hrs. 1.3 hrs.	1-141 1-141

## FILMS INSTRUCTIONS

Record this I.S. Note in M.R. 251 page B-133, M.R. 252 page B-125, M.R. 253 page B-59 and file it in M.R. 171.

**LTV** Missiles and Electronics Group  
AM General Division

April 24, 1987

VIA CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

Mr. Ken W. Schang  
Director Vehicle Environmental  
and Safety  
American Motors Corporation  
14250 Plymouth Road  
Detroit, MI 48232

Dear Mr. Schang:

During the years 1984-85 AM General built 5,645 FJ-8C 1/2-ton postal vans which were subsequently leased to the U. S. Postal Service by American Motors Leasing Corp. under the terms of Contract GS-00S-64456. These vehicles were equipped with 6 cylinder, 258 cubic inch engines purchased from AMC.

In the past 2 1/2 years, the U.S.P.S. has reported 75 instances of engine compartment fires. The fires appear to be originating in the area of the carburetor/manifold. In some instances, the damage is quite severe, destroying the vacuum hoses, valve covers and melting the carburetor. Although there have not been any personal injuries, the U.S.P.S. Office of Fleet Management feels that this is an inordinate number of fires.

Apparently the alleged defect involves an inherent flaw in the design of the engine. We are informed that a like problem has been experienced with the Jeep product line. AMG engineering has repeatedly attempted to get AMC Vehicle Safety Enforcement involved - to no avail.

Since American Motors Leasing Corporation is the prime contractor, your cooperation is necessary in order to get to the root of the problem and resolve this issue to the satisfaction of all concerned.

Due to the potentially serious nature of this matter, we would appreciate an immediate reply.


Sincerely,

LTV Missiles and Electronics Group  
AM General Division

*A. W. MacDonald*

A. W. MacDonald  
Director Logistics Operations

041:fa



600 371

**American Motors Corporation**

Vehicle Environmental and Safety Affairs  
14250 Plymouth Road  
Detroit, Michigan 48232  
(313) 493-3048

April 27, 1987

**COPY**

Mr. Phillip W. Davis, Director  
Office of Defects Investigation  
Enforcement  
National Highway Traffic Safety  
Administration  
400 Seventh Street, S.W.  
Washington, D. C. 20590


Reference: PE87-024

Dear Mr. Davis:

This communication confirms our discussions at a meeting with you and your staff on April 8, 1987, and also responds to your March 30, 1987, letter (PE87-024) regarding alleged engine compartment fires in model FJ-8C 1/2-ton delivery van vehicles manufactured by AM General, a division of LTV Aerospace and Defense Company.

We reviewed this matter and found that the engine location relative to the firewall and the material composition and routing of the vacuum harness in the AM General vehicles are significantly different from the American Motors Corporation (AMC) vehicles equipped with the 258 CID 6-cylinder engine. As agreed, this, in addition to the information recently provided to NHTSA by AM General on this issue, precludes the need for AMC to submit the data requested in your March 30, 1987, letter.

Sincerely,



James A. Carlson, Director  
Vehicle Safety and Health  
Regulatory Affairs

cc: Mr. Richard Reed, NHTSA

JJP/au

4363v

bcc: K. I. Gluckman  
J. J. Podorsek  
M. W. Stucky  
NHTSA Chron



400-372

# PRELIMINARY

## MEMO TO FILE

ISSUE: NHTSA's March 30, 1987, letter, PE87-024  
Alleged Fires in 1984 AM General 1/2-Ton Post Office Vehicles

- CHRON:
- o AMC received NHTSA's March 30, 1987, letter on April 2, 1987. The scope of the inquiry involves all 1984-1987 AMC vehicles equipped with the 258 CID, 6-cylinder engine which was also used in the 1/2-ton postal vehicles, model FJ-8C.
  - o On April 3, 1987, Mr. Mallett met with D. Weiher, AM General, Livonia, Michigan, to discuss AM General's March 30, 1987, campaign of 5,645 model FJ-8C 1/2-ton delivery van: equipped with the 258 CID, 6-cylinder engine supplied by AMC. The purpose of the campaign is to correct and re-route the vacuum harness assembly so it will not come in contact with the engine exhaust manifold and eventually catch on fire. Mr. Weiher provided copies of AM General's campaign information and response to P. Davis, NHTSA.
  - o On April 10, 1987, Messrs. Mallett and Podorsek visited AM General Livonia, Michigan, to meet with G. derPlibosian and to inspect an FJ-8C 1/2-ton van equipped with the 258 CID, 6-cylinder engine. It appeared that the vacuum hose assembly was not routed the same way as 1987 AMC Eagle equipped with a 258 CID, 6-cylinder engine (see photographs). Also, the hose material was different between the Eagle and the FJ-8C (i.e. plastic for Eagle and rubber for the postal van).
  - o On April 23, 1987, Messrs. T. Cheema, AMC Engine Engineer and J. Podorsek visited AM General, Livonia, Michigan, to meet with M. Kunz and to re-inspect the FJ-8C vehicle. Mr. Cheema confirmed the differences between the AMC and AM General vehicles (see attachment).
  - o On April 28, 1987, AMC received from LTV, Mr. MacDonald's, April 24, 1987 letter regarding an alleged inherent flaw in the design of the engine and his apparent awareness of a like problem allegedly in Jeep vehicles with the same 6-cylinder engine.

J. J. Podorsek  
May 4, 1987

4420v/au

000373

1. 100T58K,  
SUB. 258 C.I.D Post Office vehicle.

As we discussed earlier today I am confirming the differences between our own released vacuum hoses and A.M General's veh. that we saw this morning

- 1- Location of dash panel extension is such that 90% of the vac. harness has been rerouted and reconnected by A.M. Gen
- 2- The Rubber tubes supplier 'EMCO' is not an approved source to A.M.C
- 3- Vac. harnesses were not tied down as we required in our veh

Specifically, there were four vac. tubes which were routed by A.M. Gen., such that going behind the engine and drooping over the manifolds. Where our tubes are routed over the front of the engine to avoid the manifolds

Pl. find enclosed backup info The process sheets will be forwarded to you as soon as they become available

Tahir S. Green

33622

4-23-'87

000374





**American Motors Corporation**

Vehicle Environmental and Safety Affairs  
14250 Plymouth Road  
Detroit, Michigan 48232  
(313) 483-3048

May 11, 1987

Mr. A. W. MacDonald, Director  
Logistics Operations  
LTV Missiles and Electronics Group  
AM General Division  
701 West Chippewa Avenue  
South Bend, Indiana 46680-2841

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

Dear Mr. MacDonald:

This communication responds to your April 24, 1987, letter regarding the design of the 6-cylinder, 258 CID engine, manufactured by American Motors Corporation (AMC). These engines were sold for use in the 1984 AM General 1/2-ton, Model FJ-8C, delivery vans. In your letter you indicate that some of these vans have experienced engine compartment fires and you assert that there is an inherent flaw in the design of this engine. Also, you indicate you were informed that "a like problem (emphasis added) has been experienced with the Jeep product line," which also uses the 258 CID, 6-cylinder engine.

Please be advised that we are not aware of any design flaws inherent in the engines sold for use in the 1984 AM General 1/2-ton, Model FJ-8C, delivery vans. Moreover, Jeep vehicles equipped with the 258 CID, 6-cylinder engine have not experienced the engine compartment fire problem identified for the 1984 AM General 1/2-ton, Model FJ-8C, delivery van.

In March 1987, AM General Division of LTV Aerospace and Defense Company, informed NHTSA of a voluntary campaign of 5,645, 1984 AM General 1/2-ton, Model FJ-8C, delivery vans equipped with the 258 CID, 6-cylinder engine. AM General determined that if the vacuum harness assembly hoses in the engine compartment of these vehicles become loose or fall off, they could come in contact with the exhaust manifold and could result in a fire.

We have investigated this matter and found that the engine compartment design of the 1984 Model FJ-8C delivery van is completely different than that used in Jeep vehicles. The routing of the vacuum harness assembly in Jeep vehicles equipped with the 258 CID, 6-cylinder engine differs substantially from the routing used in the 1984 Model FJ-8C delivery van. In Jeep vehicles, the vacuum harness assembly is routed over the engine and is appropriately secured to avoid hose contact with the engine intake and exhaust manifolds.

Further, we found that AM General sourced the hoses in the harness assembly to a vendor which is not used by AMC for such parts. Finally, we found that the routing and the securing of the vacuum harness assembly used in the 1984 Model FJ-8C delivery van was designed, developed and implemented into production by AM General, and not by AMC.




000375

In summary, AMC has found nothing to support the existence of an alleged inherent design flaw in the 258 CID, 6-cylinder engine. As noted above, there are major differences in the engine vacuum harness assembly configurations used in Jeep vehicles and in 1984 AM General 1/2-ton, Model FJ-8C, delivery vans. Jeep products have not experienced the engine compartment fire problem identified for the AM General Model FJ-8C. Further, based on the vacuum harness design utilized in our Jeep vehicles, we do not expect that such a problem could develop.

AMC believes that the action by AM General to campaign 1984 AM General 1/2-ton, Model FJ-8C, delivery vans because of the defect they identified was appropriate. The nature of the defect which precipitated this campaign involves decisions made by AM General in the design, sourcing and assembly of the vacuum harness, and not an inherent flaw in the design of the 258 CID, 6-cylinder engine.

Sincerely,



James A. Carlson, Director  
Vehicle, Safety and Health  
Regulatory Affairs

cc: R. Houtman, Assistant General Counsel

JJP/au

4417v

006376



# Missiles and Electronics Group

AM General Division

cc: G. DeP: lbes:ar  
R. M. Johnson  
G. A. Maddox  
F. I. Masten  
L. F. Miller  
H. R. Sandler  
G. W. Scharback  
D. P. Weiher

August 25, 1987

MR. James A. Carlson, Director  
Vehicle, Safety and Health  
Regulatory Affairs  
14250 Plymouth Road  
Detroit, MI 48232

Dear Mr. Carlson:

This is in further reference to my letter of April 24, 1987 concerning engine compartment fires on USPS FJ-8C vehicles and your reply of May 11, 1987.

The USPS is continuing to experience engine compartment fires on their FJ-8C fleet. Over 95 fires have been recorded to date. These vehicles contain the 6-cylinder, 258 CID engine manufactured by American Motors Corp. (AMC) which was dressed with emission hoses by AM General. Extensive research, testing and evaluation has been conducted by our Product Engineering Department to determine the exact cause of these fires. The following chronology defines these activities:

- March 14, 1987 - Steel fuel feed line provided to USPS at AMG expense - Retrofit Program has been completed.
- December 3, 1986 - AMG Product Engineering released rework instructions to Field Service Department for rerouting of vacuum hoses.
- February 6, 1987 - USPS received technical bulletin from AMG Field Service Department describing the rework and rerouting of vacuum hoses.
- February 26, 1987 - USPS issued a formal complaint to Mr. Phillip Davis, Office of Defects Investigation of NHTSA, concerning FJ-8C engine compartment fires.
- March 24, 1987 - AM General Safety Committee determined that a safety related defect existed requiring notification to NHTSA.
- March 30, 1987 - Notification letters of safety related defect sent to NHTSA and USPS. NHTSA assigned Campaign #87V-041.
- April 2, 1987 - A notice from NHTSA was received by Mr. D. P. Weiher of AM General Product Assurance informing us that a defect investigation was in progress.

000377

Apr: 2, 1987 - Letter sent to Mr. Richard Reed of the Office of Defects Investigation explaining that AM General is conducting Campaign #87V-041 to retrofit all suspect vehicles. Per telecon with Mr. Reed and Mr. D. P. Weiher this satisfies their letter of request for information dated April 2, 1987

April 10, 1987 - USPS Field Modification Bulletin #VMO-05-87 issued to correct vacuum hoses on all FJ-8C vehicles.

Subsequently, we received additional reports of engine compartment fires after the vacuum hose rework and rerouting was performed. These incidents were directly related to excessive oil on/or about the plastic valve cover. Our field history of fire incidents cite several cases where excessive oil was noticed after the fires. However, most vehicle fires destroyed such evidence. It is our field service experience that the old AMC plastic valve cover P/N 8933002393 does warp due to exposure to engine heat and that warpage results in leakage of engine oil onto the cover and related adjacent components, hoses and hardware.


We are well aware, that a; extensive change was made by AMC on securing this plastic valve cover to the cylinder block. Since heat exposure is to be expected for valve covers and since oil leakage due to valve cover warpage is an undesirable design characteristic, we feel it is incumbent for us to advise you of NHTSA's awareness of this campaign so that any future unfavorable publicity directed toward the AMC Division of Chrysler Corporation can be avoided.

Therefore, we are requesting AMC to supply a quantity of 5,645 new improved 10-fastener mounted valve cover kits P/N 8983503343 on a "no charge" basis to AMG's Field Service Department, South Bend, IN for use in conjunction with Campaign #87V-041.

AMG is confident that Mr. Iacocca's commitment "We just want to be the best" is in harmony with this request.

Sincerely,

LTV Missiles & Electronics Group  
AM General Division

  
A. W. MacDonald  
Director, Logistics Operations

Copy furnished: Mr. L. Iacocca, Chief Executive Officer  
Chrysler Corporation, Detroit, MI

Mr. Paul Rosenak, USPS, Washington D.C.

000378



UNITED STATES POSTAL SERVICE  
Delivery Services Department  
475 L'Enfant Plaza, SW  
Washington, DC 20260-7200

September 21, 1987

Mr. Frank Henderson  
Director, Government Vehicle  
Sales - Washington  
1100 Connecticut Avenue, N.W.  
Washington, DC 20036-4104

Dear Mr. Henderson:

In accordance to your recent telecon with Paul Rosenak of my staff, we have enclosed a copy of the letter written by LTV Missiles and Electronics Group, AM General Division regarding the excessive number of engine compartment fires experienced by the Postal Service.

Any assistance you can provide to resolve this issue will be greatly appreciated. Should additional information be required, please contact Mr. Rosenak.

Sincerely,

*Robert K. St. Francis*

Robert K. St. Francis  
Director, Office of Fleet Management

Enclosure

1341516171

SEP 23 1987

000379



CHRYSLER  
CORPORATION

October: 6, 1987

Mr. Robert K. St. Francis  
Director, Office of Fleet  
Management  
U.S. Postal Service  
475 L'Enfant Plaza, SW, Rm. 7217  
Washington, D.C. 20260

Dear Bob:

In reference to your letter of September 21st, I had the opportunity to discuss the engine compartment fires experienced by the U.S. Postal Service with our people in Detroit during my visit last week.

The opinion rendered was that the engine fire problem was the responsibility of AM General rather than AMC as the FJ-8C was originally purchased from AM General.

On the other hand, matters involving AMC and your vehicles should be addressed to this office as we now have the responsibility for American Motors' products.

Please advise any time we may be of assistance.

Sincerely,

F. R. Henderson  
Director, Government and  
Military Vehicle Sales

Enclosure

FRH:pfa

bcc: H.L. Barton  
J.V. Tracy /

RECEIVED

OCT 8 1987

J. V. TRACY

000-380

CONTACT REPORT OF USPS 11-10-87 & 11-11-87

11-11-87

PEOPLE

ENGINE COMPARTMENT FIRES ON US POSTAL SERVICE FJ-3C VEHICLES (1/2 TON DELIVERY VAN-BUSSE BY AIA GENERAL WITH 258 6 CYL ENGINE BY RMC)

POPULATION

APPROX. 100 ENGINE FIRES OUT OF TOTAL NATIONAL FLEET OF 5645.

OPERATING

HEAVY STOP AND GO DRIVING WITH FREQUENT ENGINE OFF'S. SOME ROUTES REQUIRES 500 TO 800 STOPS PER DAY. IF DELIVERY DIKTATES CARRIER MUST LEAVE. VAN ENGINE MUST BE TURNED OFF.

MAINT.

230 VEHICLE MAINTENANCE FACILITIES NATION-WIDE. MOST OF THE REPAIR WORK. REPAIRS ARE CONTRIBUTED OUT WHERE PRACTICAL IN REPAIRS NOT USED TO FACILITY. PREVENTIVE MAINTENANCE IS PERFORMED EVERY 6 MONTHS. IN BETWEEN INTERVALS REPAIRS ARE PERFORMED AS NEEDED.

HISTORY

USPS

TESTING:

- 1 VEHICLE WAS INSTRUMENTED WITH 10 THERMO COUPLES AND A METAL FRAME W/ PLEXIGLASS PANEL "DOG HOUSE". A HOLE WAS DRILLED IN TOP OF DOG HOUSE WHERE A METAL TUBE WAS INSERTED SO OIL WOULD DRIP ON THE #4 EXHAUST RUNNER. VEHICLE WAS THEN PUT ON A DYNAMOMETER TO SIMULATE VARIOUS DRIVING CONDITIONS.

- WORST CASE OPERATING MODE WAS USED (1/5 MPH STEADY STATE 18500 GVW/UP 3 TO 4% GRADE). EXHAUST MANIFOLD STARTED GLOWING IN CENTER AND WORKED OUT TO ENDS OF MANIFOLD WITHIN APPROX. 10-15 MINUTES. APPROX. 1/2 TSP/POUNCE OF OIL WAS PUT ON MANIFOLD, AFTER ENGINE WAS TURNED OFF. OIL IGNITED AND CONTINUED TO BURN GETTING WORSE WAS USED TO BE EXTINGUISHED AND OIL CONTINUED SPILLING TIMES

ILLEGIBLE

000381

-2-

USPS

TEST-CONT:

- DAD TEST MODE WAS STOP AND GO DRIVE CYCLE. ENGINE WAS TURNED OFF AND OIL IGNITED AND CONTINUED TO BURN. FIRE WAS EXTINGUISHED AND DID NOT RE-IGNITE
- ROAD TESTED VEHICLE IN STOP AND GO DRIVE CYCLE. OIL IGNITED ON MANIFOLD WHILE ENGINE AT IDLE. (FIRST TIME VEHICLE RUNNING) - ADDED MORE OIL SO = 1 DROP / 15 SECOND RATE AND DRIVE VEHICLE. ONLY SMOKE OCCURRED. TURNED ENGINE OFF AND OIL IGNITED.

CAUSE OF FIRES:

AFTER REVIEWING ALL USPS DATA, I CONCLUDED CAUSE OF FIRES COULD BE RATED INTO FIVE CATEGORIES AS FOLLOWS: (BASED ONLY ON CASES W/ PHOTO'S OR SOME TECHNICAL DESCRIPTION OF DAMAGE).

- 32 - OIL LEAK FROM VALVE COVER IGNITION ON EXHAUST MANIFOLD USUALLY NEXT TO OR JUST REAR OF CARBURETOR. WERE THEY RUNNING?
- 8 - WIREN SHORTS FROM MANIFOLD HEATER/NOON CIRCUIT
- 5 - FUEL LEAKS AT FILTER RETURN VALVE TO NYLON RETURN TUBE CONNECTION. (NOTED 39 ADDITIONAL REPORTS OF FUEL LEAKS W/O FIRES. 16 @ 1 VEHICLE MAINTENANCE FACILITY).
- 2 - VACUUM HOSE IN CONTACT W/ MANIFOLD.
- 47 TOTAL

RECOMMENDATION:

SINCE ACTION HAD ALREADY BEEN TAKEN ON THE LAST 3 CATEGORIES, THE ONLY REMAINING ISSUE IS THE VALVE COVER OIL LEAK. THIS STATION ACCOUNTED FOR 68% OF THE FBIR TOTAL (47). FLEET SHOULD BE RETROFITTED W/ NEW VALVE COVER KIT.

00F382



000383

# Field Product Report

AMC/JEEP/RENAULT  
American Motors  
Sales Corporation

Tl. and Supplier Codes

1-143

Complete Vehicle Identification Number

Sequence/Fabrication No.

Month/Year Built

1 J C B C 7 5 6 7 F T 0 2 4 2 5 7 J 1 3 8 3 7 1 9 / 8 4

Mileage

Zone/Dealer Code

Date

Submitted By (Print Name)

1 3 4 8 5 0 3 8 9 9 9 9 6 / 2 5 / 8 5 YAKUBOSKY

Condition: ENGINE OIL LEAK - VALVE COVER AREA

Cause: POOR FIT - GASKET ON OIL FILTER CAP

Correction: REPLACE CAP

Retain the last copy. Mail first three copies intact to: American Motors Corporation Service Reliability, 14250 Plymouth Rd., Detroit, Mich. 48232

AM-3814  
Rev. 5-83

000384

984 Jeep

8(N)

## Field Product Report

Tl. and Supplier Codes

1-141

Complete Vehicle Identification Number

Sequence/Fabrication No.

Month/Year Built

1VCNV15M0ET064637

1/84

Mileage

Zone/Dealer Code

Date

Submitted By (Print Name)

4020

023

7690

7/12/84

B.R. White

Condition: V/C (GASKET) LEAKING

Cause: —

Correction: Re-Seal Valve Cover

Retain bottom copy, mail top copy to American Motors Corporation Service Reliability, 14250 Plymouth Rd., Detroit, Mich. 48232

AM 2614 Rev. 9-83

000385

85 Jeep  
8 (N)

Valve Cover

Field Product Report												T1. and Supplier Codes					
Complete Vehicle Identification Number												Sequence/Fabrication No.				Month/Year Built	
1JTCNJT15W3AT149912												1-137				1	
Mileage				Zone/Dealer Code				Date				Submitted By (Print Name)					
7533				025				0478				7/16/86					
Condition: OIL LEAK AT ENGINE																	
Cause: VALVE COVER GASKET LEAKING																	
Correction: RESEALED COVER																	
Retain bottom copy, mail top copy to American Motors Corporation Service Reliability, 14250 Plymouth Rd., Detroit, Mich. 48232																	

AM 3614 Rev 9-83

000366

16 26

## DEALER TEKLINE

Adviser

RJ

Date

2-13-86

Julian

Dealer Code

4 2 2 3 0 6

Phone

Dealer

LJ. V4

COMPLETE VIN

Mileage

50000

Feb

RENAULT

Jeep

AMC

Caller

## Problem Description

258  
79 Jeep 4<sup>th</sup> rocker cover gasket sucked in

TLC

## Attempted Repairs/History

## Suggested Corrective Action

went thru list gasket procedure

Dealer called back

Follow up call

Region

Returned from Region

Advice given was:

1. Adequate as published

2. Published but deficient

3. Not published

4. Canada call

5. From MNPDC

6. From Loc. PDC

7. From Quality Analyst

Comments:

# DEALER TEKLINE

Adviser

RS

Date

6-9

Julian

aler Code

26 3446 CANADA

Phone

Dealer

Grace

COMPLETE VIN

SO Eagle

Mileage

RENAULT Jeep AMC

Caller

## Problem Description

After: 5:00

After: 6:00

valve cover leaking

TLC

1000

## Attempted Repairs/History

## Suggested Corrective Action

use adhesion primer

use studs instead of hold down screws

back out of shop + leave set for 6 hours

Diagnostic material available is:

If deficient why:

☒ Adequate

☐ Deficient

☐

Known problem no field fix

☐

Service publication deficient\*

☐

Other\*

Provide comments below

Comments:

000388

## DEALER TEKLINE

### Advisors

25

Date \_\_\_\_\_

2-27-f6

## Julien

**Dealer**

Dealer  
Royal Oak

**Dealer Code**

076

## COMPLETE VIN

**Mileage****RENAULT**

class

**ANC**

**Caller**

### Problem Description

TLC

### Attempted Repairs/History

### Suggested Corrective Action

**caller called back**

**How up call**

### 3 Region

### From Region

**Advice given was:**

**1. Adequate as published**

## 2. Published but deficient

**3. Not published**

#### 4. Canada call

## 5. From MNPDC

**From Loc. PDC**

## 7. From Quality Analysis

Comments:

600389

VI

00C390



TYPE: Warranty Litigation  
NAME: Bettie Campbell v. AMSC et al  
COURT: District Court; Santa Fe City, Santa Fe, NM  
VEHICLE: 1980 AMC Eagle; AVC385C256368  
SERVICE DATE: 12/28/83  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: Douglas Newberry  
COURT: N/A  
VEHICLE: 1980 AMC Eagle; AVC365C204404  
SERVICE DATE: 03/01/83  
DESCRIPTION: Owner alleges oil leaks at head gasket cover.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: Tommy Brenton v. Jeep Corporation et al  
COURT: District Court; Union City; Farmerville, LA  
VEHICLE: 1981 Jeep CJ-7; 1JCCM87E9BT004534  
SERVICE DATE: 09/23/81  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Small Claims  
NAME: Charles E. Burke v. AMSC  
COURT: Small Claims; Westchester City; White Plains, NY  
VEHICLE: 1981 AMC Eagle; 2CCCG385388700482  
SERVICE DATE: 09/21/84  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

000331

TYPE: Warranty Litigation  
NAME: Paul Czwalina v. AMSC et al  
COURT: Common Pleas Court; Luzerne City; Wilkes-Barre, PA  
VEHICLE: 1981 AMC Eagle; 1ACCC3552BK156797  
SERVICE DATE: 03/02/82  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: Pamela Jenkins v. AMC et al  
COURT: Common Pleas Court; Richland City; Columbia, SC  
VEHICLE: 1981 AMC Spirit; 1AMCC4350BK100264  
SERVICE DATE: 03/22/82  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: Robert Masson v. AMC et al  
COURT: Superior Court; Tompkins City; Ithaca, NY  
VEHICLE: 1981 AMC Eagle; 1ACCG5359BK112640  
SERVICE DATE: 12/05/83  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: Donald Miller v. Jeep Corporation et al  
COURT: Common Pleas Court; Luzerne City; Wilkes-Barre, PA  
VEHICLE: 1981 Jeep J-10; 1JTCM26N4B7031476  
SERVICE DATE: 11/09/81  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

000-392

TYPE: Warranty Litigation  
NAME: Dan Rapak v. AMC et al  
COURT: Superior Court; Mercer City, Trenton, NJ  
VEHICLE: 1981 AMC Eagle; 1ACCG36588K154376  
SERVICE DATE: 10/12/84  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Product Litigation  
NAME: James Stewart v. AMC et al  
COURT: Circuit Court; Dune City; Madison, WI  
VEHICLE: 1981 AMC Concord; 1AMCA08548K100579  
SERVICE DATE: 07/26/83  
DESCRIPTION: Owner alleges engine oil leak was repaired at an AMC dealership and subsequent fire damage resulted.  
ANALYSIS: No injuries reported.

TYPE: Warranty Litigation  
NAME: Calvin Leasing . AMC et al  
COURT: Superior Court; San Francisco County, San Francisco, CA  
VEHICLE: 1982 Jeep CJ-5; 1JCCM851E3CT044273  
SERVICE DATE: 11/03/83  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: P. Jean Hall v. AMC et al  
COURT: Circuit Court; Floyd County; Prestonsbury, KY  
VEHICLE: 1982 Jeep J-10; 1JTCM25N8CT045268  
SERVICE DATE: 08/16/83  
DESCRIPTION: Owner alleges engine oil leaks

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

000393

TYPE: Warranty Litigation  
NAME: GMAC v. AMC et al  
COURT: Circuit Court; Lelanau City, Lelanau, MI  
VEHICLE: 1983 Jeep Wagoneer; 1JCCJ15N5D052173  
SERVICE DATE: 12/12/83  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: Pasieczny v. AMC et al  
COURT: Circuit Court; Wayne City; Monroe, MI  
VEHICLE: 1983 AMC Eagle; 1ACCN5357dk121572  
SERVICE DATE: 06/03/85  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: David Burm v. AMC et al  
COURT: Superior Court, Kern City; Bakersfield, CA  
VEHICLE: 1984 Jeep Wagoneer; 1JCUC7551ET005833  
SERVICE DATE: 01/23/84  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: Donald L. Curry v. AMSC  
COURT: City Court; Lubbock City; Lubbock, TX  
VEHICLE: 1984 Jeep CJ-7; 1JCUM87ABET053522  
SERVICE DATE: 02/26/86  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

600-394

TYPE: Warranty Litigation  
NAME: John H. Hughes v. AMC et al  
COURT: Superior Court; San Diego City; San Diego, CA  
VEHICLE: 1984 Jeep CJ-8; 1JCUL7826ET046606  
SERVICE DATE: 05/01/84  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: Philip Kendall v. AMC et al  
COURT: N/A  
VEHICLE: 1984 Jeep Cherokee; 1JCUL7723ET000670  
SERVICE DATE: 01/02/85  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: Stephen Marcus v. AMC et al  
COURT: District Court; Worcester City; Westborough, MA  
VEHICLE: 1984 Jeep CJ-7; 1JCCM87E7ET134591  
SERVICE DATE: 09/18/85  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Warranty Litigation  
NAME: Catherine Norman v. AMC et al  
COURT: District Court; Union City; Farmville, LA  
VEHICLE: 1984 Jeep CJ-7; 1JCCM87E9ET050353  
SERVICE DATE: 12/06/84  
DESCRIPTION: Owner alleges valve cover leakage.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

000-235

TYPE: Subrogation.  
NAME: State Farm Mutual Insurance Co. v. AMC et al  
COURT: District Court; Rapid City; Alexandria, LA  
VEHICLE: 1984 Jeep CJ-7; 1JCUM87A3ET095256  
SERVICE DATE: 07/16/86  
DESCRIPTION: Owner had vehicle serviced for alleged oil leak.  
After repair, fire ensued.  
ANALYSIS: No injuries reported.

TYPE: Warranty Litigation  
NAME: Tidewater Utilities v. Jeep  
COURT: Superior Court; Mercer City; Trenton, NJ  
VEHICLE: 1984 Jeep Grand Wagoneer 1JCCJ15N7ET070841  
SERVICE DATE: 10/10/84  
DESCRIPTION: Owner alleges engine oil leaks.

ANALYSIS: This is a warranty related issue.  
No fire or injury reported.

TYPE: Subrogation  
NAME: United Farm Bureau Mutual Ins. Co. v. AMC et al  
COURT: Circuit Court; Kosciusko City; Warsaw, IN  
VEHICLE: 1984 AMC Eagle; 2CCCK3857EB701167  
SERVICE DATE: 06/28/85  
DESCRIPTION: Owner alleges fire caused by engine oil leaks.

ANA: No injuries reported.

000-395

VII

000397

711 In Motors Sales Corporation

WA CITY INVOICE - REPAIR ORDER

353-03

35 X  
CJ-7

4312 L

DATE

07/01

020381

Wendell Warren  
4170 W Spruce  
FT Wainwright AK

TOTAL

5800

1 BCC F87E9 FT 143233

03303

0063

031586

031187

X

12/12

DATE RECEIVED

13305331

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

22 22 22

14188770

22 22 22

22 22 22



STATUS  
MICROFILM  
DEALER NO  
RESUB INVOICE

ACCEPTED  
A967904  
05081  
12412

INPUT DT  
INPUT TIME  
REPAIR ORDER

05/04/87  
VIN 1J4C182EXT1182629  
FAB 8015346

WARRANTY INVL 12412

COPS IN SERV DT 06/05/86  
SELLING CLR SAME Y  
COPS INVOICE DT 08/29/85

IN SERVICE DT 06/03/86  
REPAIR DT 04/27/87  
MILEAGE 11514

INCIDENT # 1747V MESSAGE: 0000 OK TO PAY NO ADJUSTMENTS  
WARR TYPE: 12 EXPENSE CD: 71 INC CD: 1143 SUPP CD:  
OPER CO: 1382 OPEN TEXT: REPLACE VALVE COVER  
0015 ADJUST ROCKER ARMS  
PART MO: 8085503343 PART TEXT: VALVE COVER

HRS: 01.5 AMOUNT: 51.00  
001.5 17.00  
QTY: 01 AMOUNT: 27.26  
INCIDENT A TOTAL 95.26  
TOTAL INVOICE AMOUNT 95.26

000:159

MICROFILM A967904

# WV TV INVOICE - REPAIR ORDER

1. Name of customer  
2. Address  
3. City  
4. State  
5. Zip  
6. Phone  
7. Date of purchase  
8. Date of repair  
9. Name of repairman  
10. Name of shop  
11. Name of dealer  
12. Name of manufacturer  
13. Name of distributor  
14. Name of retailer  
15. Name of wholesaler  
16. Name of importer  
17. Name of exporter  
18. Name of manufacturer  
19. Name of distributor  
20. Name of retailer  
21. Name of wholesaler  
22. Name of importer  
23. Name of exporter

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

18105

James D. Zander  
P.O. Box 767  
Kila, W.

13CCF87A6FT054222

08330

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

063086

DEALER

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

36 0465 3886

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST

1965 MAINT ST